

## Part-1

### Performa for the Safety School Building (To be filled by the Head of School/ Institute)

1. Name of School : TAGORE PUBLIC SCHOOL .
2. Location : AGGAR NAGAR, BLOCK-A, FEROZEPUR ROAD, LUDHIANA
3. Plot Area : 58086 SQ. FT.
4. Plinth Area : 29997 SQ. FT.
5. Number of Storey : DOUBLE STOREY
6. Year of Construction of Building : 1975
7. Supervision of the qualified Engineer,
  - a) Name of the Engineer: MR. KRISHAN KUMAR, CIVIL ENGINEER
  - b) Address : THE LDH AGG. CO-OP H/B SOCIETY LTD. AGGAR NAGAR, LUDHIANA
  - c) Set of Structure Drawing used in the Construction if available: YES (COPY ATTACHED)
  - d) Name of the Architect:
8. Whether the building has been constructed for the purpose of :
  - a) School (Yes/ No) .....YES.....
  - b) Residential purpose and converted (Yes/ No) .....NO.....  
for use as a school
9. Materials used for Roof :
  - a) R.C.C Slabs (Yes/ No) .....YES.....
  - b) R.S. Joists and Battens (Yes/ No) .....NO.....
  - c) Wooden Joists and Battens (Yes/ No) .....NO.....
10. Materials used for walls :
  - a) Mud Mortar (Yes/ No) .....NO.....
  - b) Cement Mortar (Yes/ No) .....YES.....
  - c) Plaster (i) Lime Mortar (Yes/ No) .....NO.....  
(ii) Cement Mortar (Yes/ No) .....YES.....
11. Flooring:
  - a) Conglomerate (Yes/ No) .....YES.....
  - b) Terrazzo (Yes/ No) .....NO.....
  - c) Brick Paving (Yes/ No) .....NO.....
12. Detailed Drawing indicating dimensions of the rooms along with size and location of doors and windows  
.....MAP ATTACHED.....

Signature with stamp of  
The Head of the School/ Institute

  
PRINCIPAL  
TAGORE PUBLIC SCHOOL  
AGGAR NAGAR, LUDHIANA

PART II

(TO BE FILLED BY THE SDE OF PWD B&R DEPTT.)

**SCHOOL SAFETY CERTIFICATE**

- a) I have visited the above mentioned school on 15/06/2023 and have visually inspected it from all angle of safety and I find it fit for normal use as school building.
- b) In case any additional/alteration or expansion and modification to this building is to be carried out, the same be carried out under the supervision of a technically qualified engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is settlement of walls / foundations or safing of roofs etc. immediately inspection of the under signed be arranged to check the stability and safety of the building.
- d) This building can be safely occupied for normal use upto 31/03/2024  
(Indicate year upto which it can be used)

ਨੰਬਰ:- 158

ਮਿਤੀ:- 14/6/23

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 3  
Sub Divisional Engineer  
ਲੁਧਿਆਣਾ

1. Principal Tagore Public School Aggar Nagar Ludhiana ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਜਾਣਕਾਰੀ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ।

2. ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ. 1, ਲੇ.ਨਿ.ਵਿ., ਭ ਤੇ ਮ ਸ਼ਾਖਾ, ਲੁਧਿਆਣਾ ਜੀ ਨੂੰ ਸੂਚਨਾ ਅਤੇ ਲੋੜੀਂਦੀ ਕਾਰਵਾਈ ਹਿੱਤ ਭੇਜਿਆ ਜਾਂਦਾ ਹੈ ਜੀ।

PRINCIPAL  
TAGORE PUBLIC SCHOOL  
AGGAR NAGAR, LUDHIANA

ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ  
ਉਸਾਰੀ ਮੰਡਲ ਨੰ: 3  
ਲੇ.ਨਿ.ਵਿ. ਭ ਤੇ ਮ ਸ਼ਾਖਾ,  
ਲੁਧਿਆਣਾ

**Part-II**  
(To be filled by S.D.E of P.W.D B&R Department)  
**Building Safety Report**

Name of School :- TAGORE PUBLIC SCHOOL

I have <sup>Mrs</sup> visited the above mentioned School building along with Sh. Pragati Kapoor on dated 15/6/23 and have visually inspected. It seems visually safe subject to the following observation & conditions.

- a. Parameters to check the stability and safety of building such as Architectural Drawings, Bearing capacity, Foundation details Structural Drawings, Technical Specifications, Test Reports of Material used Quality Control reports and Certificate from Engineer in Charge for Construction are not available.
- b. In case of any addition, alteration of expansion and modification of this building are done; certificate may be re-obtained after completion from undersigned.
- c. In case the building is affected by flood or if there is settlement of walls/ foundation or sagging of roofs etc., immediate inspection of the undersigned be arranged to check the stability and safety of the building.
- d. A separate certificate regarding Fire Fighting should be obtained from the competent authority.
- e. A separate certificate regard Electrical Work should be obtained from the competent authority.
- f. The owner of the building/Management is fully responsible regarding safety of building from all angels in spite of this report.
- g. The covered area of the building is 29997 Sq. Ft.
- h. This report is not valid for legal purpose.
- i. As per Government order no. 5/13/2018-3BR3/1294287/3 dated 10-08-2018 for issue of building safety certificate Para 2.0 (a), this certificate as requested by school authority is issued for period of 1 years up to 31/03/2024

  
Junior Engineer

  
ਪ੍ਰਿੰਸੀਪਲ ਟੀਚਰ  
ਕਮਿਸ਼ਨਰੀ ਮੰਡਲ ਨੰ: 3  
ਲੋ.ਟਿ.ਵਿ.ਡ ਤੇ ਮ.ਭਾ.ਭਾ.  
ਲੁਧਿਆਣਾ।